



Flow Meter

Measuring Range SCFM: 0.1 - 530 & 0.12 - 23,275

Pressure Range: up to 232 psig & up to 580 psig

Models: Stationary & X2

Industrial Process Solutions - Compressed Air & Gas Sales & Service in PA, CT, NJ, NY, DE, MD, WV

Industrial Process Solutions

DPM Series

Instrumentation -

Measuring Range PDP: -112 to +122 Â°F Flow Meters

Pressure Range: -14.5 to 232 psig

Dew Point Monitors

Models: Portable, Stationary, X2

Manufacturer: BEKO [\[Product Details...\]](#)

Air Leak Monitors

-
Multi-Function Air Monitor

-
Hydrocarbon Monitor

-
Oxygen Analyzers

-
Carbon Dioxide/Monoxide